

Case Photo	IMG_0564.jpg	01/06/2023	Vent screens to be replaced	3.915335 MB
Case Photo	IMG_0565.jpg	01/06/2023	Vent screens to be replaced	3.516139 MB
Case Photo	IMG_0566.jpg	01/06/2023	Weather protection around light fixture	2.224763 MB
Case Photo	IMG_0567.jpg	01/06/2023	Shed addition at back of dwelling	2.969667 MB
Case Photo	IMG_0568.jpg	01/06/2023	Weather protection needed around wall ac unit	3.210432 MB
Case Photo	IMG_0569.jpg	01/06/2023	Weather protection needed around wall ac unit	2.774048 MB
Case Photo	IMG_0868.jpg	02/10/2023	Front of dwelling	3.583450 MB
Case Photo	IMG_0869.jpg	02/10/2023	Damage at roof	2.869228 MB
Case Photo	IMG_0870.jpg	02/10/2023	Damage at roof	2.687864 MB
Case Photo	IMG_1156.jpg	03/10/2023	Roof damage from tree	3.058604 MB
Case Photo	IMG_1157.jpg	03/10/2023	Roof damage from tree	3.006412 MB
Case Photo	IMG_1484.jpg	04/10/2023	Tree damage at roof	2.798128 MB
Case Photo	IMG_1735.jpg	05/10/2023	Tree damage	2.674938 MB
Case Photo	IMG_1736.jpg	05/10/2023	Tree damage	2.464409 MB

## NOTES

TYPE	DATE	CREATED BY	NOTE
RE-INSPECTION - Activity Note	01/06/2023	Arrion Gildersleeve	1/6/23. I arrived onsite with BI Lovato to assist with inspection. A tree fell on the house and damaged the electrical panel and roof. The p/o met with us and smud and the arborist. SMUD cut power at the pole. The arborist started cutting down the tree.
General Case Information	01/09/2023	Paul Lovato	I arrived onsite on 1/6/23 and from the front of the dwelling I could see the roof eave and the mast for the electrical panel have been damaged from a tree that had fallen. As I was assessing the damage and taking pictures, SMUD showed up and stated they would be cutting the power to the dwelling units. I then went to the tenants in the units and explained the power will be cut due to the damage. The tenant upstairs stated that he would find other arrangements and the tenant downstairs had a hard time speaking English. She then called her husband and I spoke with him. He stated that his wife sleeps with oxygen. I let him know he needed to try to find other arrangements until repairs were made. As I was walking out, the owner of the property showed up with a tree removal company. I talked with him about the repairs and the tenants in the property. He stated that he was going to pull the permit for the power first since the roof damage was only the eaves. He stated he would get the power on, then pull another permit for the roof repairs.
General Case Information	01/09/2023	Paul Lovato	Permit issued: RES-2300347 E-Permit: - Overhead service, Repair weather head/masthead work.
General Case Information	02/10/2023	Paul Lovato	I arrived onsite on 2/10/23 at 8:30 am to verify work has not started with out building permits. CDD permit is still in issued status for the power release. Tree has been removed but no work or permits have been issued for the repairs to the roof. Will set out a re-inspection for 30 days to verify status of dwelling.
MEMO/NOTE - Activity Note	03/03/2023	Doug Pierson	ADDITIONAL COMPLAINT: See File #: 23-007269 - AFTER THE WINTER STORM WHEN A TREE WAS RESTING ON THE HOUSE FOR WEEKS AND