

Corrective Action: Work has been done without the benefit of a PERMIT. This work must be removed or properly Permitted and Approved by the City of Sacramento. This Violation List may be partial and does not exclude any code violations which may become apparent during further inspections or during the necessary rehab/repair work. Other building structural, electrical, plumbing or mechanical code violations may be identified upon further inspection. Permit required for repairs and rehab, and may be obtained at 300 Richards Blvd. 3rd floor.



PHOTOGRAPH DECLARATION I declare under penalty of perjury under the laws of the State of California that I took the attached photograph. The picture truly and accurately depicts the condition of the property located at the address stated below as it existed on that date.

Date Taken: 04/11/2024

Taken By: Paul Lovato

Address: 4880 T ST

Case Number: 23-009185

Corrective Action: Work has been done without the benefit of a PERMIT. This work must be removed or properly Permitted and Approved by the City of Sacramento. This Violation List may be partial and does not exclude any code violations which may become apparent during further inspections or during the necessary rehab/repair work. Other building structural, electrical, plumbing or mechanical code violations may be identified upon further inspection. Permit required for repairs and rehab, and may be obtained at 300 Richards Blvd. 3rd floor.



PHOTOGRAPH DECLARATION I declare under penalty of perjury under the laws of the State of California that I took the attached photograph. The picture truly and accurately depicts the condition of the property located at the address stated below as it existed on that date.

Date Taken: 04/11/2024

Taken By: Paul Lovato

Address: 4880 T ST

Case Number: 23-009185